DELPHI SYSTEMS CORP.

CORRECTIVE MEASURES PROPOSAL

FIGURE 30

Figure 30: Soil 1,1-DCA Concentrations Isocontours





LEGEND:

- DP0160 — SOIL SAMPLING LOCATION WITH ONE OR MORE SAMPLE RESULTS LESS THAN GROUNDWATER PROTECTION CRITERIA
- DP0129 — SOIL SAMPLING LOCATION WITH ONE OR MORE SAMPLE RESULTS GREATER THAN GROUNDWATER PROTECTION CRITERIA (AF)
- AREA WITH LESS THAN REMEDIATION CRITERIA
- AREA WITH GREATER THAN OR EQUAL TO REMEDIATION CRITERIA WITH ATTENUATION FACTOR (AF)
- AREA INFERED BEYOND EXTENT OF DATA
- ISOCONTOUR GROUNDWATER PROTECTION CRITERIA

NOTES:

1. ISOCONCENTRATION LINES BASED ON DATA COLLECTED AT THE SITE IN AUGUST 2005 THROUGH AUGUST 2006.
2. ISOCONCENTRATION LINES ARE BASED ON GEOSTATISTICAL INTERPRETATION OF RESULTS FROM SHOWN SAMPLE LOCATIONS. ACTUAL CONDITIONS MAY VARY.
3. DCA: 1,1-DICHLOROETHANE; DCE: 1,1-DICHLOROETHENE.
4. AF: ATTENUATION FACTOR WITHIN SOIL COLUMN (3.3).

N
W E
S

0 40 80 120 160
SCALE IN FEET

HALEY & ALDRICH

DELPHI CORPORATION
FORMER BATTERY OPERATIONS, 1201 N. MAGNOLIA
ANAHEIM, CALIFORNIA
32486-011

SOIL
1,1-DCA CONCENTRATION
ISOCONTOURS

SCALE: AS SHOWN
AUGUST 2007

FIGURE 30

G:\32486\011-CMP-CORRECTIVE MEASURES PROPOSAL\CAD\32486-SOIL_CONTOURS-DCE_DCA_R1.DWG