

Please Note: The original version of this figure includes colorized features and shading. A black and white copy of the figure should not be used because it may not accurately represent the information presented.

Legend

- Chatsworth Formation Monitoring Well
- Shallow Monitoring Well
- Property Boundary Line
- Streams
- TTF Interim Status Facility (Area addressed in the Interim Status Facility Closure)
- Area of Buried Debris (1981)
- Area of Sediment (1981)
- 1 Excavation Perimeter (1982) With Excavation Number
- Approximate Location Where Anomalies Identified by ICF Kaiser (1993) Were Exhumed
- Former Concrete Ponds/Pads
- Soil Sample Collected by Harding Lawson Associates (1981-1982)
- Soil Sample Collected by GWRC, 1993-1994
- Soil Sample Collected by Haley & Aldrich/DTSC (2005)
- Area I Burn Pit (SWMU 4.8) Boundary
- Earthen Pond

N
W E
S

0 40 80 120 160
SCALE IN FEET

DRAFT

HALEY & ALDRICH

AIBP SWMU 4.8 RFI WORKPLAN
BOEING SANTA SUSANA FIELD LABORATORY
VENTURA COUNTY, CALIFORNIA

HISTORICAL SOIL SAMPLING LOCATIONS AREA I BURN PIT - SWMU 4.8

SCALE: AS SHOWN
OCTOBER 2006

FIGURE 2

G:\Graphics\Projects\26472 - Boeing Roc\ROC_GIS_20023\96_SSFL_TTF_2006_IMWP_HA_T